



English

**Steer-Aid™
Power Steering Conditioner and Leak Stop**

- **Conditions and Revitalizes Seals**
- **Stops and Prevents Leaks**
- **Prevents Foaming**

Read warnings on back panel.

Net Contents 12 fl. oz. (355 mL)

No. 05345

Prolongs the life of the power steering unit by restoring the elasticity of the seals, stopping internal leaks and squeals due to aged and dry seals. Non-clogging. Non-corrosive. Non-foaming. Does not affect viscosity of fluid in power steering unit.

Not for use in Honda or Acura vehicles.

Use *Steer-X™ Power Steering Stop-Leak and Conditioner* item #403015.

DIRECTIONS: *Read entire label before use.* Add enough Steer-Aid™ to maintain proper fluid levels in power steering unit reservoir. Check reservoir periodically.

WARNING: Contains Petroleum Distillate 64742-53-6/64742-52-5/64742-65-0 and Diocetyl Adipate 103-23-1. Deliberate misuse by concentrating and inhaling the contents may be harmful or fatal. Use only in a well ventilated area. Keep away from heat and flame. Avoid contact with skin. **FIRST AID:** In case of eye or skin contact, flush with large amounts of water for at least 15 minutes. If swallowed, **DO NOT** induce vomiting. If too much is breathed, remove to fresh air. For severe overexposure, call a physician immediately.

KEEP AWAY FROM CHILDREN.

All used and unused product should be disposed of in conformance with local, state, and federal regulations. For additional information, consult the Material Safety Data Sheet for this product.

Spanish

**Steer-Aid™
Acondicionador y reparador de pérdidas para dirección hidráulica**

- **Acondiciona y revitaliza los sellos**
- **Elimina y previene las pérdidas**
- **Evita la formación de espuma**

Lea las advertencias en el dorso.

Contenido neto: 12 onzas líquidas (355 mL)

No. 05345

Prolonga la vida de la unidad de dirección de potencia restaurando la elasticidad de los sellos, eliminando las pérdidas internas y los ruidos causados por sellos viejos y secos. No produce atascamientos. No corrosivo. No produce espuma. No afecta la viscosidad del líquido de la unidad de dirección de potencia.

No apto para vehículos Honda o Acura.

Use el *acondicionador y reparador de pérdidas para dirección de potencia Steer-X™*, artículo # 403015.

INDICACIONES: *Lea completamente la etiqueta antes de usarlo.* Agregue suficiente Steer-Aid™ como para mantener el nivel adecuado de líquido en el recipiente de la unidad de dirección de potencia. Revise el recipiente periódicamente.

ADVERTENCIA: Contiene petróleo destilado 64742-53-6/64742-52-5/64742-65-0 y dioctil adipato 103-23-1. El abuso deliberado concentrando e inhalando el contenido puede ser nocivo o fatal. Usar únicamente en un área bien ventilada. Mantener lejos del calor y de las llamas. Evite el contacto con la piel. **PRIMEROS AUXILIOS:** Si entra en contacto con los ojos o la piel, enjuáguelos con mucha agua durante 15 minutos por lo menos. Si se traga, **NO** induzca vómito. Si se inhala demasiado, diríjase al aire libre. En caso de exposición severa, llame inmediatamente a un médico.

MANTENER ALEJADO DEL ALCANCE DE LOS NIÑOS.

Todo el producto utilizado y sobrante deberá desecharse de acuerdo con las normas nacionales, estatales y locales. Para mayor información, consulte la Hoja de Datos de Seguridad del Material para este producto.