

DIRECTIONS: Read entire label before using this product. 1. Use caution when using on or around energized equipment. 2. Do not spray directly on plastics. 3. Hold can 10" to 12" from mold surface. 4. For best results, do not overspray. 5. Apply a light, even film to mold surface as needed when sticking occurs. 6. To avoid marked parts, do not over apply.

INSTRUCCIONES: Lea toda la etiqueta antes de usar este producto. 1. Actúe con cautela al utilizar en un equipo conectado a la energía eléctrica o cerca de éste. 2. No rocíe directamente sobre superficies plásticas. 3. Mantenga la lata a una distancia de 10" a 12" de la superficie a rociar. 4. Para obtener mejores resultados, no rocíe una cantidad excesiva de producto. 5. Aplique una capa fina y pareja sobre la superficie del molde en caso de adherencia. 6. Para evitar marcas, no aplique el producto en exceso.

Danger: Flammable aerosol. Contains gas under pressure; may explode if heated. Causes skin irritation. Causes serious eye irritation. May cause respiratory irritation. May cause drowsiness or dizziness. Suspected of causing cancer. May damage fertility or the unborn child. May cause damage to organs (kidney, liver, nervous system) through prolonged or repeated exposure.



Precautionary Statements: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Do not spray on an open flame or other ignition source. Pressurized container: Do not pierce or burn, even after use. Use with adequate ventilation. Open doors and windows or use other means to ensure a fresh air supply during use and while product is drying. If you experience any symptoms listed on this label, increase ventilation or leave the area. Do not breathe mist or vapor. Wear protective gloves/protective clothing/eye protection/face protection. Wash thoroughly after handling. Store in a well-ventilated place. Store locked up. Protect from sunlight. Do not expose to temperatures exceeding 50°C/122°F. Exposure to high temperature may cause can to burst. When exposed to extreme heat or hot surfaces, vapors may decompose to harmful or fatal corrosive gases such as hydrogen bromide. Dispose of contents/container in accordance with local/regional/national regulations.

First Aid: If on skin: Wash with plenty of water. If skin irritation occurs: Get medical attention. Take off contaminated clothing and wash before reuse. If inhaled: Remove person to fresh air and keep comfortable for breathing. Call a poison center/doctor if you feel unwell. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention. If exposed or concerned: Get medical attention.

Contains dimethyl ether 115-10-6, n-propyl bromide 106-94-5, and lecithin 68910-52-1. Deliberate misuse by concentrating and inhaling the contents is illegal and can be harmful or fatal. Inhalation abuse can cause death. For additional information, consult SDS for this product.

Electrical Shock Hazard: This metal can will conduct electricity. Keep away from all live electrical sources. Failure to observe this warning may result in serious injury and/or flash fire.

Peligro: Aerosol inflamable. Contiene gas a presión; puede explotar si se calienta. Provoca irritación cutánea. Provoca irritación ocular grave. Puede irritar las vías respiratorias. Puede provocar somnolencia o vértigo. Susceptible de provocar cáncer. Puede perjudicar la fertilidad o dañar al feto. Puede provocar daños en los órganos (riñón, hígado, sistema nervioso) tras exposiciones prolongadas o repetidas.

Consejos de Prudencia: Procurarse las instrucciones antes del uso. No manipular antes de haber leído y comprendido todas las precauciones de seguridad. Mantener alejado del calor/de chispas/de llamas al descubierto/de superficies calientes. - No fumar. No vaporizar sobre una llama al descubierto o cualquier otra fuente de ignición. Recipiente a presión. No perforar ni quemar, incluso después del uso. Usar con ventilación adecuada. Abra las puertas y ventanas y utilice otros medios para asegurar la provisión de aire fresco al utilizar el producto y mientras se esté secando. Si presenta algunos de los síntomas enumerados en esta etiqueta, aumente la ventilación o deje el área. No respirar nieblas o vapores. Usar guantes/ropa de protección/equipo de protección para los ojos/la cara. Lávese cuidadosamente después de la manipulación. Almacenar en un lugar bien ventilado. Guardar bajo llave. Proteger de la luz solar. No exponer a una temperatura superior a 50 °C/122 °F. La exposición a altas temperaturas puede provocar que la lata estalle. Al exponerlo al calor extremo o superficies calientes, los vapores pueden descomponerse en gases corrosivos y tóxicos como el bromuro de hidrógeno. Eliminación de contenidos / contenedor en consonancia con los reglamentos locales / regionales / nacionales pertinentes.

Primeros Auxilios: En caso de contacto con la piel: Lavar con abundante agua. Si ocurre irritación de la piel: Busque atención médica. Quitar la ropa contaminada y lavarla antes de volverla a usar. En caso de inhalación: Transportar la persona al aire libre y mantenerla en una posición que le facilite la respiración. Llamar a un CENTRO DE TOXICOLOGÍA o a un médico si la persona se encuentra mal. En caso de contacto con los ojos: Enjuagar con agua cuidadosamente durante varios minutos. Quitar las lentes de contacto cuando estén presentes y pueda hacerse con facilidad. Proseguir con el lavado. Si persiste la irritación de los ojos: Busque atención médica. En caso de exposición demostrada o supuesta: Busque atención médica.

Su mal uso deliberado, concentrando e inhalando su contenido es ilegal y puede ser perjudicial o fatal. La inhalación abusiva puede causar la muerte. Para mayor información, consulte la Hoja de Datos de Seguridad para este producto.

Peligro de Descarga Eléctrica: Esta lata de metal puede conducir la electricidad. Manténgala alejada de todas las fuentes eléctricas vivas. El incumplimiento de esta advertencia puede resultar lesiones graves y/o incendio repentino.

VOC Category: Mold Release Coating | MIR Limit: 1.10

©2017 CRC Industries, Inc., 885 Louis Dr., Warminster, PA 19374
800-521-3168 (Technical Info) • 800-272-4620 (Customer Care) • 215-442-6260 (SDS) • www.crcindustries.com Made in U.S.A.



Lecithin Mold Release

Desmoldante de Lecitina

Paintable
Fast Drying
Prevents Sticking
Meets FDA Reg. 21 CFR 175.300

Puede Pintarse
Secado Rápido
Evita la Adherencia



No. 03306
Net Wt./Peso Neto
12 oz (340 g)

To review S.D.S.: Tear (DO NOT CUT) label along these perforations and fold back label. After viewing, reattach label. Do not completely remove label until can is empty. Para revisar la Hoja de Datos de Seguridad (HDS): Rasgue (NO CORTE) la etiqueta, siguiendo estas perforaciones y dóblala hacia atrás. Al terminar, vuelva a pegar la etiqueta. No la retire completamente hasta que la lata esté vacía.

1. Identification

Product identifier: Lecithin Mold Release

Product code: 03306

Recommended use: Mold release

Restrictions: None known.

Manufactured or sold by:

CRC Industries, Inc., 885 Louis Drive, Warminster, PA 18974

Phone: 215-674-4300

Emergency phone number: CHEMTREC - 24 HOURS: 800-424-9300

2. Hazard(s) identification

Physical hazards	Flammable aerosols (Category 2) Gases under pressure (Liquefied gas)
Health hazards	Skin corrosion/irritation (Category 2) Serious eye damage/eye irritation (Category 2) Carcinogenicity (Category 2) Reproductive toxicity (Category 1B) Specific target organ toxicity, single exposure (Category 3 respiratory tract irritation, narcotic effects) Specific target organ toxicity, repeated exposure (Category 2)
Label elements (see front side of label)	

3. Composition/information on ingredients

Hazardous components

Chemical name	CAS number	%
dimethyl ether	115-10-6	60 – 70
n-propyl bromide	106-94-5	20 – 30
lecithin	68910-52-1	3 – 5

(Specific chemical identity and/or percentage of composition has been withheld as a trade secret.)

4. First-aid measures

Inhalation: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Oxygen or artificial respiration if needed. Call a POISON CENTER or doctor/physician if you feel unwell.

Skin contact: Remove contaminated clothing and wash skin with soap and water. If skin irritation occurs: Get medical attention.

Eye contact: Immediately flush eyes with plenty of water for at least 15 minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Get medical attention if irritation develops and persists.

Ingestion: In the unlikely event of swallowing contact a physician or poison control center. Rinse mouth.

Most important symptoms/effects: Skin and severe eye irritation. Vapors have a narcotic effect and may cause headache, fatigue, dizziness and nausea. May cause respiratory irritation.

Special treatment needed: Provide general supportive measures and treat symptomatically. Keep victim under observation. Symptoms may be delayed.

5. Fire-fighting measures

Suitable extinguishing media: Foam. Dry chemical. Carbon dioxide (CO2).

Unsuitable extinguishing media: None known.

Specific hazards: When exposed to extreme heat or hot surfaces, vapors may decompose to harmful or fatal corrosive gases such as hydrogen bromide.

Special protective equipment and precautions for firefighters: Firefighters must use standard protective equipment including flame retardant coat, helmet with face shield, gloves, rubber boots, and in enclosed spaces, SCBA. Containers should be cooled with water to prevent vapor pressure build up.

6. Accidental release measures

Personal precautions: Do not touch damaged containers or spilled material unless wearing appropriate protective equipment. Do not breathe mist or vapor. Ventilate closed spaces before entering them.

Containment and cleaning up: Eliminate all ignition sources. Keep combustibles away from spilled material. Wipe up with absorbent material. Clean surface thoroughly to remove residual contamination. Prevent entry into waterways, sewer, basements or confined areas. Avoid release to the environment.

7. Handling and storage

Handling: Pressurized container: Do not pierce or burn, even after use. Do not smoke while using this product. Do not breathe mist or vapor. Avoid contact with eyes, skin, and clothing. Avoid prolonged exposure. Pregnant or breastfeeding women must not handle this product. Use only in well-ventilated areas. Wear appropriate personal protective equipment. Wash hands thoroughly after handling.

Storage: Store in a cool, dry place (below 122°F/50°C) and out of direct sunlight. Do not handle or store near an open flame, heat or other sources of ignition. This material can accumulate static charge which may cause spark and become an ignition source. Store in a well-ventilated place, away from incompatible materials.

8. Exposure controls/personal protection

Occupational exposure limits

Components	Type	Value
n-propyl bromide	TWA	0.1 ppm
dimethyl ether	TWA	1000 ppm

Appropriate engineering controls: Mechanical ventilation or local exhaust ventilation is recommended.

Individual protection measures:

Eye/face protection: Wear safety glasses with side shields (or goggles).

Skin protection: Wear protective gloves such as PVA, Viton/butyl, or laminate film. Wear appropriate clothing to prevent skin contact.

Respiratory protection: Use a NIOSH-approved cartridge respirator with an organic vapor cartridge unless exposure is below the TLV. Use a self-contained breathing apparatus in confined spaces and for emergencies.

9. Physical and chemical properties

Appearance: Colorless liquid.

Odor threshold: Not available.

Melting point/freezing point: < -50 °F (< -45 °C)

Flash point: Not available.

Explosive limit - lower (%): Not available.

Vapor pressure: 139 mm Hg

Relative density: 0.78

Partition coefficient (n-octanol/water): Not available.

Decomposition temperature: Not available.

MIR: 0.68

Odor: Slight.

pH: Not available.

Initial boiling point: 160 °F (71 °C)

Evaporation rate: Not available

Explosive limit - upper (%): Not available.

Vapor density: Not available.

Solubility(ies): Insoluble in water

Auto-ignition temperature: 914 °F (490 °C)

Viscosity: Not available.

10. Stability and reactivity

Reactivity: Non-reactive

Chemical stability: Stable

Possibility of hazardous reactions: No

Conditions to avoid: Heat, flames and sparks. When exposed to extreme heat or hot surfaces, vapors may decompose to harmful or fatal corrosive gases such as hydrogen bromide. Incompatible materials.

Incompatible materials: Alkaline earth metals. Oxidizing agents. Bases. Reactive metals. Natural rubber.

Hazardous decomposition products: Hydrogen bromide. Carbon oxides.

11. Toxicological information

Information on likely routes of exposure:

Ingestion: Ingestion may cause gastrointestinal irritation, nausea, vomiting and diarrhea.

Inhalation: May cause drowsiness, dizziness, headache, nausea, and vomiting. May cause irritation to the respiratory system.

Skin contact: Causes skin irritation.

Eye contact: Causes serious eye irritation.

Symptoms related to the physical, chemical and toxicological characteristics: Skin and severe eye irritation. Vapors have a narcotic effect and may cause headache, fatigue, dizziness and nausea. May cause respiratory irritation.

Information on toxicological effects:

Acute toxicity: None known.

Respiratory sensitization: Not a respiratory sensitizer.

Skin sensitization: Not expected to cause skin sensitization.

Carcinogenicity: Suspected of causing cancer.

n-Propyl bromide NTP (Reasonably Anticipated to be a Human Carcinogen)
IARC 2B (Possibly carcinogenic to humans.)

Reproductive toxicity: May damage fertility or the unborn child.

Aspiration hazard: Not an aspiration hazard.

Chronic effects: May cause damage to the following organs through prolonged or repeated exposure: kidney, liver, nervous system.

12. Ecological information

See full SDS for additional information

13. Disposal considerations

Disposal instructions: The dispensed liquid product is not a RCRA hazardous waste. Empty container can be recycled.

Hazardous waste code: Not regulated.

14. Transport information

DOT shipping description: UN1950, Aerosols, flammable, 2.1, limited quantity

15. Regulatory information

SARA 313 n-propyl bromide

See full SDS for additional information

16. Other information

Issue date 12/28/2016

Version # 04