

A specially designed lithium 12 hydroxy stearate grease fortified with 3% moly disulfide and extreme pressure and anti-wear additives.

Contains rust, corrosion and oxidation inhibitors.

Extends life of C.V. Joints.

C.V. Joint boots should be routinely inspected for rips, cracks, etc.

**REPLACE DAMAGED BOOTS.**

It is important when replacing a boot or repairing a C.V. Joint that you follow the instructions in a repair manual for assembly or disassembly of C.V. Joint.

#### **DIRECTIONS**

1. Before removing the old boot from the shaft, draw a mark on the shaft where the boot ends.
2. Cut off the two band clamps and slice the old boot off.
3. Wipe away excess grease from joint and housing with a clean rag.
4. Be sure to clean out the remaining grease with solvent. (Use CRC Brakleen Part No. 05089 or CRC Non-Chlorinated Brakleen Part No. 05088 for best results.)
5. Use low pressure air to dry joint thoroughly or allow to air-dry for five minutes or more.
6. Pack joint by working grease into the parts and inside the housing. Make sure grease is well dispersed throughout joint and housing.

The majority of vehicles require 4 oz. of grease per joint. However, there are joints that specify more or less amounts of grease. Check with dealer or repair manual for proper amounts required for your vehicle.

#### **7. ONE-PIECE BOOT INSTALLATION:**

Carefully slide the new boot over shaft. Stretch large end of boot over joint housing. Line up opposite end of boot with mark (see step 1) and tighten clamps. If boot is twisted, untwist by loosening clamps and then re-tighten. If boot is collapsed, loosen clamps and carefully slip a screwdriver between boot and housing to release the trapped air.

#### **SPLIT BOOT INSTALLATION:**

To keep from contaminating the seam with grease, spread boot open and carefully install over drive shaft. Use the mark (see Step 1) to place boot properly. Follow split boot manufacturer instructions for complete installation.

**WARNING:** Contains Paraffinic Oil 64742-65-0, Lithium Soap 7620-77-4, Antimony Diethylthiocarbamate 800987-5045, Mineral