

RTV 硅密封胶 - 透明 (加压)
二甲基(硅氧烷与聚硅氧烷): $\geq 70\%$
二氧化硅: 7 - 13%
加氢处理中蒸馏油 (石油): 5 - 10%
乙基三乙酰氧基硅烷: 1 - 5%
甲基三乙酰氧基硅烷: 1 - 5%

警告



压力容器: 遇热可爆。造成皮肤刺激。造成眼刺激。对水生生物有害。对水生生物有害并具有长期持续影响。

[预防措施]

远离热源/火花/明火/热表面。禁止吸烟。切勿穿孔或焚烧, 即使不再使用。作业后彻底洗手。戴防护手套。避免释放到环境中。

[事故响应]

如皮肤沾染: 用大量肥皂和水清洗。具体治疗(见本标签)。如发生皮肤刺激: 求医/就诊。脱去被污染的衣物, 清洗后方可重新使用。如进入眼睛: 用水小心冲洗几分钟。如戴隐形眼镜并可方便地取出, 取出隐形眼镜。继续冲洗。如仍觉眼刺激: 求医/就诊。

[安全储存]

防日晒。不可暴露在超过 $50^{\circ}\text{C}/122^{\circ}\text{F}$ 的温度下。

[废弃处置]

按照地方/区域/国家/国际规章处置内装物/容器。

供应商: CRC Industries, Inc.

电话: 1-215-674-4300

地址: 885 Louis Dr. Warminster, PA 18974 USA

化学事故应急电话码: +86 532 83889090

DIRECTIONS: Read entire label before using this product.

1. Clean and dry all surfaces. Remove any oil and grease prior to application. Sealant adheres best to clean, unpainted surfaces.
2. Pull tab, then adjust cap following min/max arrow to control bead width. Press handle to apply sealant.
3. If further tooling is required, complete within 5 minutes. Remove excess sealant immediately with a dry paper towel.
4. Sealant "skins" in approximately 10 minutes, dries to the touch in one hour, and fully cures and bonds in 24 hours. Optimum strength is achieved in 7 days.
5. If gasket is not used in assembly, apply sealant to surface of one part and allow skin to form before assembling parts.
6. After sealant is completely cured, excess material can be removed by trimming with a sharp blade. Avoid undercutting the sealant.
7. Resealable: If contents are not used, wipe the top of nozzle and firmly replace cap. If clogged, use small tool to clear tip.
8. Not recommended for use involving continuous immersion in gasoline or head gasketing operations.

PR14055 Rev14A