

Bright Zinc-It® 即冷镀锌

丙酮: 30 - 40% 正丁烷: 10 - 20%

丙烷: 10 - 20% 甲苯: 10 - 20% 锌,基本原理: 10 - 20%

危 险



极易燃气溶胶。压力容器: 遇热可爆。造成皮肤刺激。造成严重眼刺激。怀疑因吸入对生育能力或胎儿造成伤害。可能造成昏昏欲睡或眩晕。长期或反复接触可能损害器官(中枢神经系统)。吞咽及进入呼吸道可能致命。对水生生物有毒。对水生生物有毒并具有长期持续影响。

[预防措施]

在使用前获取特别指示。在读懂所有安全防范措施之前切勿搬动。远离热源/火花/明火/热表面。禁止吸烟。切勿喷洒在明火或其他点火源上。切勿穿孔或焚烧,即使不再使用。不要吸入烟雾或蒸气。不要吸入气体。只能在室外或通风良好之处使用。作业后彻底洗手。戴防护手套/穿防护服/戴防护眼罩/戴防护面具。避免释放到环境中。

[事故响应]

如误吞咽: 立即呼叫解毒中心或医生。不要诱导呕吐。如皮肤沾染: 用大量肥皂和水清洗。具体治疗(见本标签)。如发生皮肤刺激: 求医/就诊。脱掉沾染的衣服,清洗后方可重新使用。如进入眼睛: 用水小心冲洗几分钟。如戴隐形眼镜并可方便地取出,取出隐形眼镜。继续冲洗。如仍觉眼刺激: 求医/就诊。如误吸入: 将人员转移到新鲜空气处,并保持呼吸舒适的体位。如感觉不适,呼叫解毒中心/医生。如接触到或有疑虑: 求医/就诊。收集溢出物。

[安全储存]

存放在通风良好的地方。保持容器密闭。防日晒。不可暴露在超过 50°C/122°F 的温度下。存放处须加锁。

[废弃处置]

按照地方/区域/国家/国际规章处置内装物/容器。

参见安全数据表。

供应商: CRC Industries, Inc. 电话: 1-215-674-4300

地址: 885 Louis Dr. Warminster, PA 18974 USA

化学事故应急电话码: +86 532 83889090

DIRECTIONS: Read entire label before using this product. 1. Do not apply while equipment is energized. 2. For optimum results, remove dirt, oil, rust or corrosion with a wire brush, abrasive or CRC® Cleaner. Allow surface to dry. 3. Shake can well before using. Repeat as necessary to ensure smooth, even coverage. 4. Hold can 12-15 inches from surface and spray until desired area is completely covered. 5. For increased protection, apply additional coats after each coat dries. 6. To prevent valve from clogging, turn can upside down and spray 2-5 seconds to clear zinc from valve and button.