SAFETY DATA SHEET

1. Identification

Product identifier TAC 2® Adhesive Chain Lubricant

Other means of identification

03076 **Product code**

Recommended use Industrial chain lubricant

Recommended restrictions None known.

Manufacturer/Importer/Supplier/Distributor information

CRC Industries. Inc. Company name

Address 885 Louis Dr.

Warminster, PA 18974 US

Telephone

215-674-4300 **General Information Technical** 800-521-3168

Assistance

Customer Service 800-272-4620 24-Hour Emergency 800-424-9300 (US)

(CHEMTREC) 703-527-3887 (International) Website www.crcindustries.com

2. Hazard(s) identification

Physical hazards Flammable aerosols Category 1

> Gases under pressure Liquefied gas Skin corrosion/irritation Category 2 Serious eye damage/eye irritation Category 2B

Reproductive toxicity (fertility) Category 2

Category 3 narcotic effects Specific target organ toxicity, single exposure

Aspiration hazard Category 1 Category 2

Hazardous to the aquatic environment, acute

Hazardous to the aquatic environment,

long-term hazard

OSHA defined hazards Not classified.

Label elements

Environmental hazards

Health hazards



Signal word Danger

Extremely flammable aerosol. Contains gas under pressure; may explode if heated. May be fatal if **Hazard statement**

swallowed and enters airways. Causes skin irritation. Causes eye irritation. May cause

drowsiness or dizziness. Suspected of damaging fertility. Toxic to aquatic life. Toxic to aquatic life

Category 2

with long lasting effects.

Precautionary statement

Prevention

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Do not spray on an open flame or other ignition source. Pressurized container: Do not pierce or burn, even after use. Do not apply while equipment is energized. Extinguish all flames, pilot lights and heaters. Vapors will accumulate readily and may ignite. Use only with adequate ventilation; maintain ventilation during use and until all vapors are gone. Open doors and windows or use other means to ensure a fresh air supply during use and while product is drying. If you experience any symptoms listed on this label, increase ventilation or leave the area. Avoid breathing mist or vapor. Wear protective gloves/protective clothing/eye protection/face protection. Wash thoroughly after handling. Avoid release to the environment.

Response

If swallowed: Immediately call a poison center/doctor. Do NOT induce vomiting. If on skin: Wash with plenty of water. If skin irritation occurs: Get medical advice/attention. Take off contaminated clothing and wash before reuse. If inhaled: Remove person to fresh air and keep comfortable for breathing. Call a poison center/doctor if you feel unwell. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention. If exposed or concerned: Get medical advice/attention. Collect spillage.

Storage

Store in a well-ventilated place. Store locked up. Protect from sunlight. Do not expose to temperatures exceeding 50°C/122°F. Exposure to high temperature may cause can to burst.

Disposal

Dispose of contents/container in accordance with local/regional/national regulations.

Hazard(s) not otherwise classified (HNOC)

None known.

3. Composition/information on ingredients

Mixtures

Chemical name	Common name and synonyms	CAS number	%
2-methylpentane		107-83-5	30 - 40
liquefied petroleum gas		68476-86-8	20 - 30
naphtha (petroleum), hydrotreated light		64742-49-0	10 - 20
petrolatum		8009-03-8	5 - 10
n-hexane		110-54-3	3 - 5
lubricating oils (petroleum), C15-30, hydrotreated neutral oil-based		72623-86-0	1 - 3
white mineral oil		8042-47-5	1 - 3

Specific chemical identity and/or percentage of composition has been withheld as a trade secret.

4. First-aid measures

Inhalation Remove victim to fresh air and keep at rest in a position comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

Remove contaminated clothing. Rinse skin with water/shower. If skin irritation occurs: Get medical Skin contact

advice/attention. Wash contaminated clothing before reuse.

Eye contact

Immediately flush eyes with plenty of water for at least 15 minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Get medical attention if irritation develops and persists.

Call a physician or poison control center immediately. Rinse mouth. Do not induce vomiting. If

vomiting occurs, keep head low so that stomach content doesn't get into the lungs.

Most important symptoms/effects, acute and delayed

Ingestion

Aspiration may cause pulmonary edema and pneumonitis. May cause drowsiness and dizziness. Headache. Nausea, vomiting. Irritation of eyes. Exposed individuals may experience eye tearing, redness, and discomfort. Skin irritation. May cause redness and pain.

Indication of immediate medical attention and special treatment needed

General information

Provide general supportive measures and treat symptomatically. Keep victim under observation. Symptoms may be delayed.

IF exposed or concerned: Get medical advice/attention. Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves. Show this safety data sheet to the doctor in attendance.

5. Fire-fighting measures

Water fog. Foam. Dry chemical powder. Carbon dioxide (CO2). Suitable extinguishing media

Unsuitable extinguishing media

Do not use water jet as an extinguisher, as this will spread the fire.

Specific hazards arising from the chemical

Contents under pressure. Pressurized container may rupture when exposed to heat or flame. During fire, gases hazardous to health may be formed.

Special protective equipment and precautions for firefighters

Firefighters must use standard protective equipment including flame retardant coat, helmet with face shield, gloves, rubber boots, and in enclosed spaces, SCBA.

Fire-fighting equipment/instructions General fire hazards

In case of fire: Stop leak if safe to do so. Move containers from fire area if you can do so without risk. Containers should be cooled with water to prevent vapor pressure build up.

Extremely flammable aerosol. Contents under pressure. Pressurized container may rupture when exposed to heat or flame.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Keep out of low areas. Many gases are heavier than air and will spread along ground and collect in low or confined areas (sewers, basements, tanks). Wear appropriate protective equipment and clothing during clean-up. Avoid breathing mist or vapor. Emergency personnel need self-contained breathing equipment. Do not touch damaged containers or spilled material unless wearing appropriate protective clothing. Ventilate closed spaces before entering them. Local authorities should be advised if significant spillages cannot be contained. For personal protection, see section 8 of the SDS.

Methods and materials for containment and cleaning up

Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area). Keep combustibles (wood, paper, oil, etc.) away from spilled material. This product is miscible in water. Prevent product from entering drains. Stop the flow of material, if this is without risk. Wipe up with absorbent material (e.g. cloth, fleece). Clean surface thoroughly to remove residual contamination. For waste disposal, see section 13 of the SDS.

Environmental precautions

Avoid release to the environment. Inform appropriate managerial or supervisory personnel of all environmental releases. Prevent further leakage or spillage if safe to do so. Avoid discharge into drains, water courses or onto the ground.

7. Handling and storage

Precautions for safe handling

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Pressurized container: Do not pierce or burn, even after use. Do not use if spray button is missing or defective. Do not spray on a naked flame or any other incandescent material. Do not smoke while using or until sprayed surface is thoroughly dry. Do not cut, weld, solder, drill, grind, or expose containers to heat, flame, sparks, or other sources of ignition. Use caution around energized equipment. The metal container will conduct electricity if it contacts a live source. This may result in injury to the user from electrical shock and/or flash fire. Avoid breathing mist or vapor. Avoid contact with eyes, skin, and clothing. Avoid prolonged exposure. Pregnant or breastfeeding women must not handle this product. Should be handled in closed systems, if possible. Use only in well-ventilated areas. Wear appropriate personal protective equipment. Wash hands thoroughly after handling. Avoid release to the environment. Observe good industrial hygiene practices. For product usage instructions, please see the product label.

Conditions for safe storage, including any incompatibilities

Level 3 Aerosol.

Pressurized container. Protect from sunlight and do not expose to temperatures exceeding 50°C/122 °F. Do not puncture, incinerate or crush. Do not handle or store near an open flame, heat or other sources of ignition. This material can accumulate static charge which may cause spark and become an ignition source. Store in a well-ventilated place. Store away from incompatible materials (see Section 10 of the SDS).

8. Exposure controls/personal protection

Occupational exposure limits

The following constituents are the only constituents of the product which have a PEL, TLV or other recommended exposure limit. At this time, the other constituents have no known exposure limits.

US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000)

Components	Type `	Value	Form
naphtha (petroleum), hydrotreated light (CAS 64742-49-0)	PEL	400 mg/m3	
,		100 ppm	
n-hexane (CAS 110-54-3)	PEL	1800 mg/m3	
,		500 ppm	
petrolatum (CAS 8009-03-8)	PEL	5 mg/m3	Mist.

Material name: TAC 2® Adhesive Chain Lubricant

03076 Version #: 03 Revision date: 01-24-2017 Issue date: 04-10-2015

or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Preserved by eyewash station. vidual protection measures, such as personal protective equipment Eye/face protection Wear safety glasses with side shields (or goggles). Skin protection	Components		ype			Value	Form
Components		Р	EL			5 mg/m3	Mist.
2-methylpentane (CAS STEL 1000 ppm 107-33-5) TWA 500 ppm 101-33-5) TWA 500 ppm 101-33-5) TWA 500 ppm 101-33-5 101-33-5) TWA 500 ppm 101-33-5 1							
107-38-5 TWA 500 ppm	Components	T	ype			Value	Form
Inhalable fraction Smg/m3 Smg/		S	TEL			1000 ppm	
C15-3.0, hydrotreated moutral oil-based (CAS 10-54-3)						• •	
n-hexane (CAS 110-54-3)	C15-30, hydrotreated neutral oil-based (CAS	Т	WA			5 mg/m3	Inhalable fraction.
Detrolatum (CAS TWA 5 mg/m3 Inhalable fraction. 8009-03-8) White mineral oil (CAS TWA 5 mg/m3 Inhalable fraction. 8008-04-7-5) Walue Form		Т	WA			50 ppm	
white mineral oil (CAS TWA 5 mg/m3 Inhalable fraction. 8042-47-5) US. NIOSH: Pocket Guide to Chemical Hazards Components Type	petrolatum (CAS	Т	WA				Inhalable fraction.
Components Type Value Form Some many many many many many many many many	white mineral oil (CAS	Т	WA			5 mg/m3	Inhalable fraction.
2-methylpentane (CAS Ceiling 1800 mg/m3 107-83-5)						Value	Form
107-83-5) TWA 350 mg/m3 100 ppm 100 p							
naphtha (petroleum), hydrotreated light (CAS 64742-49-0) n-hexane (CAS 110-54-3) ropertolatum (CAS 8009-03-8) TWA TWA TWA TWA TWA TWA TWA TW		_		-		J	
naphtha (petroleum), hydrotreated light (CAS 64742-49-0) n-hexane (CAS 110-54-3) petrolatum (CAS 8009-03-8) white mineral oil (CAS 8009-03-8) white mineral oil (CAS 8002-47-5) TWA TWA TWA TWA TWA TWA TWA TW							
naphtha (petroleum), hydrotreated light (CAS 64742.49-0) n-hexane (CAS 110-54-3) TWA TWA 100 ppm		Т	WA			•	
hydrotreated light (ČAS 64742-49-0) n-hexane (CAS 110-54-3) petrolatum (CAS 8009-03-8) petrolatum (CAS 8009-03-8) TWA 5 mg/m3 Mist. white mineral oil (CAS 8010-64-8) TWA 5 mg/m3 Mist. white mineral oil (CAS 8010-64-8) TWA 5 mg/m3 Mist. ogical limit values ACGIH Biological Exposure Indices Components Value Determinant Specimen Sampling Time n-hexane (CAS 110-54-3) 0.4 mg/l 2.5-Hexanedio n, without hydrolysis * - For sampling details, please see the source document. osure guidelines US - California OELs: Skin designation n-hexane (CAS 110-54-3) US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. Ocan be absorbed through the sk						100 ppm	
n-hexane (CAS 110-54-3) TWA TWA TWA TWA TWA TWA TWA TW	hydrotreated light (CAS	Т	WA			400 mg/m3	
n-hexane (CAS 110-54-3) petrolatum (CAS 8009-03-8) petrolatum (CAS 8TEL 10 mg/m3 Mist. 8009-03-8) TWA 5 mg/m3 Mist. 8009-03-8) TWA 5 mg/m3 Mist. 8004-247-5) TWA 5 mg/m3 Mist. 8004-247-50 TWA 5 mg/m3 Mist. 8004-247-247-247-247-247-247-247-247-247-24	0.1.12.100)					100 ppm	
petrolatum (CAS 8009-03-8) TWA 5 mg/m3 Mist. white mineral oil (CAS 8TEL 10 mg/m3 Mist. white mineral oil (CAS 8TEL 10 mg/m3 Mist. **TWA 5 mg/m3 Mist.	n-hexane (CAS 110-54-3)	Т	WA			• •	
petrolatum (CAS 8009-03-8) TWA 5 mg/m3 Mist. white mineral oil (CAS 8TEL 10 mg/m3 Mist. white mineral oil (CAS 8TEL 10 mg/m3 Mist. 8042-47-5) TWA 5 mg/m3 Mist. ogical limit values ACGIH Biological Exposure Indices Components Value Determinant Specimen Sampling Time n-hexane (CAS 110-54-3) 0.4 mg/l 2,5-Hexanedio n, without hydrolysis * - For sampling details, please see the source document. osure guidellines US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Preyewash station. vidual protection measures, such as personal protective equipment Eye/face protection Wear safety glasses with side shields (or goggles).	m nexame (ex le 110 e 1 e)	·	• • • •			•	
TWA STEL 10 mg/m3 Mist. white mineral oil (CAS 8042-47-5) TWA 5 mg/m3 Mist. 10 mg/m3 Mist. Mist. 10 mg/m3 Mist. Mist. Mist. 10 mg/m3 Mist. M		S	TEL			• •	Mist.
white mineral oil (CAS 8042-47-5) TWA 5 mg/m3 Mist. Nogical limit values SACGIH Biological Exposure Indices Components Value Determinant Specimen Sampling Time	333 33 37	Т	WA			5 mg/m3	Mist
TWA 5 mg/m3 Mist. logical limit values	white mineral oil (CAS					•	
ACGIH Biological Exposure Indices Components Value Determinant Specimen Sampling Time n-hexane (CAS 110-54-3) 0.4 mg/l 2,5-Hexanedio n, without hydrolysis * - For sampling details, please see the source document. osure guidelines US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Occupant of the short of t				•		J	
ACGIH Biological Exposure Indices Components Value Determinant Specimen Sampling Time n-hexane (CAS 110-54-3) 0.4 mg/l 2,5-Hexanedio n, without hydrolysis * - For sampling details, please see the source document. osure guidelines US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. Oropriate engineering should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Preyewash station. vidual protection measures, such as personal protective equipment Eye/face protection Wear safety glasses with side shields (or goggles).		Į	WA			5 mg/ms	IVIISt.
Components Value Determinant Specimen Sampling Time n-hexane (CAS 110-54-3) 0.4 mg/l 2,5-Hexanedio n, without hydrolysis * - For sampling details, please see the source document. osure guidelines US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. Oropriate engineering should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Preyewash station. Widual protection measures, such as personal protective equipment Eye/face protection Wear safety glasses with side shields (or goggles).	~						
n-hexane (CAS 110-54-3) 0.4 mg/l 2,5-Hexanedio Urine * n, without hydrolysis * - For sampling details, please see the source document. ** osure guidelines US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. ** oropriate engineering trols Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Preyewash station. ** vidual protection measures, such as personal protective equipment Eye/face protection Wear safety glasses with side shields (or goggles).							
n, without hydrolysis * - For sampling details, please see the source document. * osure guidelines US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. Can be absorbed through the skin. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Preyewash station. *Vidual protection Wear safety glasses with side shields (or goggles). Skin protection	Components	Value		Determinant	Specimer	Sampling	Time
US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Previous protection weasures, such as personal protective equipment Eye/face protection Wear safety glasses with side shields (or goggles).	n-hexane (CAS 110-54-3)	0.4 mg/l		n, without	Urine	*	
US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Previous protection wear safety glasses with side shields (or goggles). Skin protection	* - For sampling details, ple	ase see the source of	docı	ıment.			
US - California OELs: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. US ACGIH Threshold Limit Values: Skin designation n-hexane (CAS 110-54-3) Can be absorbed through the skin. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Previous protection wear safety glasses with side shields (or goggles). Skin protection	osure guidelines						
n-hexane (CAS 110-54-3) Can be absorbed through the skin. Can be absorbed the skin. Can be absorbed through the skin. Can be absorbed t	-	n designation					
n-hexane (CAS 110-54-3) Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Proceedings and protection measures, such as personal protective equipment Eye/face protection Can be absorbed through the skin.	n-hexane (CAS 110-54	-3)	iana		absorbed th	rough the skin.	
Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Previous protection measures, such as personal protective equipment Eye/face protection Wear safety glasses with side shields (or goggles).			J -		absorbed th	rough the skin	
should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits exposure limits have not been established, maintain airborne levels to an acceptable level. Process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits expo	·	•	entil			-	ne used Ventilation rates
Eye/face protection Wear safety glasses with side shields (or goggles). Skin protection		should be match or other engined exposure limits	should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation or other engineering controls to maintain airborne levels below recommended exposure limits. I exposure limits have not been established, maintain airborne levels to an acceptable level. Prov				
Skin protection			-				
·	-	, 3		(3 33 - 7		
and the contract of the contra	Skin protection Hand protection	Wear protective	glo	ves such as: Nitrile	Neoprene. \	/iton/butyl.	

Other

Wear appropriate chemical resistant clothing.

Respiratory protection If engineering controls are not feasible or if exposure exceeds the applicable exposure limits, use a

> NIOSH-approved cartridge respirator with an organic vapor cartridge. Use a self-contained breathing apparatus in confined spaces and for emergencies. Air monitoring is needed to

determine actual employee exposure levels.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

Observe any medical surveillance requirements. When using do not smoke. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants.

9. Physical and chemical properties

Appearance

Liquid. Physical state Aerosol. **Form** Blue. Color

Mild petroleum. Odor **Odor threshold** Not available. Ηα Not available. < -76 °F (< -60 °C) Melting point/freezing point

Initial boiling point and boiling

range

118.4 °F (48 °C) estimated

Flash point < 0 °F (< -17.8 °C) Tag Closed Cup

Evaporation rate Fast.

Flammability (solid, gas) Not available. Upper/lower flammability or explosive limits Flammability limit - lower 1 % estimated

(%)

Flammability limit - upper

(%)

8 % estimated

1528.7 hPa estimated Vapor pressure

Vapor density > 1 (air = 1)

0.71 Relative density Negligible. Solubility (water) Partition coefficient Not available.

(n-octanol/water)

437 °F (225 °C) estimated **Auto-ignition temperature**

Decomposition temperature Not available. Not available. Viscosity (kinematic) 82.7 % estimated Percent volatile

10. Stability and reactivity

The product is stable and non-reactive under normal conditions of use, storage and transport. Reactivity

Chemical stability Material is stable under normal conditions.

Possibility of hazardous

reactions

No dangerous reaction known under conditions of normal use.

Heat, flames and sparks. Contact with incompatible materials. Conditions to avoid

Incompatible materials Strong oxidizing agents.

No hazardous decomposition products are known. **Hazardous decomposition**

products

11. Toxicological information

Information on likely routes of exposure

May cause drowsiness and dizziness. Headache. Nausea, vomiting. Prolonged inhalation may be Inhalation

harmful.

Skin contact Causes skin irritation.

Eye contact Causes eye irritation.

Ingestion Droplets of the product aspirated into the lungs through ingestion or vomiting may cause a serious

chemical pneumonia.

Symptoms related to the physical, chemical and toxicological characteristics

Aspiration may cause pulmonary edema and pneumonitis. May cause drowsiness and dizziness. Headache. Nausea, vomiting. Irritation of eyes. Exposed individuals may experience eye tearing,

> 5 mg/l, 4 hours

50000 mg/kg

redness, and discomfort. Skin irritation. May cause redness and pain.

Information on toxicological effects

Acute toxicity May be fatal if swallowed and enters airways.

Components	Species	Test Results			
naphtha (petroleum), hydrotreated light (CAS 64742-49-0)					
<u>Acute</u>					
Dermal					
LD50	Rabbit	> 2000 mg/kg			
Inhalation					
LC50	Rat	61 mg/l, 4 Hours			
Oral					
LD50	Rat	> 5000 mg/kg			
n-hexane (CAS 110-54-3)					
<u>Acute</u>					
Dermal					
LD50	Rabbit	> 1300 mg/kg			
Inhalation					
LC50	Rat	< 48000 ppm, 4 Hours			
Oral					
LD50	Rat	15840 mg/kg			
petrolatum (CAS 8009-03-8)					
<u>Acute</u>					
Dermal	D-LL:	> 0000 mm/l/m			
LD50	Rabbit	> 2000 mg/kg			
Inhalation	Det	> 20 mm// 4 hours			
LC50	Rat	> 20 mg/l, 4 hours			
Oral	Det	2000			
LD50	Rat	> 2000 mg/kg			
white mineral oil (CAS 8042-	47-5)				
<u>Acute</u> Dermal					
LD50	Rabbit	> 2000 mg/kg			
Inhalation	Nabbit	2000 mg/kg			
ililialation					

Rat

Rat

Skin corrosion/irritation Causes skin irritation.
Serious eye damage/eye Causes eye irritation.

irritation

LC50

Oral LD50

Respiratory sensitization Not a respiratory sensitizer.

Skin sensitization This product is not expected to cause skin sensitization.

Germ cell mutagenicityNo data available to indicate product or any components present at greater than 0.1% are

mutagenic or genotoxic.

Carcinogenicity This product is not considered to be a carcinogen by IARC, ACGIH, NTP, or OSHA.

Material name: TAC 2® Adhesive Chain Lubricant

SDS US

^{*} Estimates for product may be based on additional component data not shown.

IARC Monographs. Overall Evaluation of Carcinogenicity

lubricating oils (petroleum), C15-30, hydrotreated neutral 3 Not classifiable as to carcinogenicity to humans.

oil-based (CAS 72623-86-0) white mineral oil (CAS 8042-47-5)

3 Not classifiable as to carcinogenicity to humans.

US. National Toxicology Program (NTP) Report on Carcinogens

US. OSHA Specifically Regulated Substances (29 CFR 1910.1001-1050)

Not regulated.

Reproductive toxicity Suspected of damaging fertility.

Specific target organ toxicity -

May cause drowsiness and dizziness.

single exposure

Aspiration hazard

Specific target organ toxicity -

Not classified.

repeated exposure

May be fatal if swallowed and enters airways. If aspirated into lungs during swallowing or vomiting,

may cause chemical pneumonia, pulmonary injury or death.

Chronic effects Prolonged inhalation may be harmful.

12. Ecological information

Toxic to aquatic life with long lasting effects. **Ecotoxicity**

Components		Species	Test Results
2-methylpentane (CAS	S 107-83-5)		
Aquatic			
Acute			
Crustacea	EC50	Daphnia	1 - 10 mg/l, 48 hours
Fish	LC50	Fish	1 - 10 mg/l, 96 hours
naphtha (petroleum),	hydrotreated light (CAS 64742-49-0)	
Aquatic			
Acute			
Crustacea	EC50	Daphnia	1 - 10 mg/l, 48 hours
Fish	LC50	Fish	1 - 10 mg/l, 96 hours
n-hexane (CAS 110-5	4-3)		
Aquatic			
Fish	LC50	Fathead minnow (Pimepha	les promelas) 2.101 - 2.981 mg/l, 96 hours

^{*} Estimates for product may be based on additional component data not shown.

Persistence and degradability

No data is available on the degradability of this product.

Bioaccumulative potential

Partition coefficient n-octanol / water (log Kow)

3.74 2-methylpentane n-hexane 3.9

Bioconcentration factor (BCF)

naphtha (petroleum), hydrotreated light 10 - 25000

Mobility in soil No data available.

Other adverse effects No other adverse environmental effects (e.g. ozone depletion, photochemical ozone creation

potential, endocrine disruption, global warming potential) are expected from this component.

13. Disposal considerations

Disposal of waste from residues / unused products If discarded, this product is considered a RCRA ignitable waste, D001. Collect and reclaim or dispose in sealed containers at licensed waste disposal site. Contents under pressure. Do not puncture, incinerate or crush. Do not allow this material to drain into sewers/water supplies. Do not contaminate ponds, waterways or ditches with chemical or used container. Dispose in accordance with all applicable regulations.

Hazardous waste code

D001: Waste Flammable material with a flash point <140 F

Contaminated packaging

Since emptied containers may retain product residue, follow label warnings even after container is emptied. Empty containers should be taken to an approved waste handling site for recycling or

disposal.

14. Transport information

DOT

UN number UN1950

UN proper shipping name Aerosols, flammable, Limited Quantity

Transport hazard class(es)

Class 2.1 Subsidiary risk -Label(s) 2.1

Packing group Not applicable.

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

Special provisionsN82Packaging exceptions306Packaging non bulkNonePackaging bulkNone

IATA

UN number UN1950

UN proper shipping name Aerosols, flammable, Limited Quantity

Transport hazard class(es)

Class 2.1 Subsidiary risk -

Packing group Not applicable.

ERG Code 10L

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

Allowed with restrictions.

Other information

Passenger and cargo

aircraft

Cargo aircraft only Allowed with restrictions.

IMDG

UN number UN1950

UN proper shipping name AEROSOLS, LIMITED QUANTITY

Transport hazard class(es)

Class 2 Subsidiary risk -

Packing group Not applicable.

Environmental hazards

Marine pollutant No.

EmS Not available.

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

15. Regulatory information

US federal regulations This product is a "Hazardous Chemical" as defined by the OSHA Hazard Communication

Standard, 29 CFR 1910.1200.

TSCA Section 12(b) Export Notification (40 CFR 707, Subpt. D)

Not regulated.

SARA 304 Emergency release notification

Not regulated.

US. OSHA Specifically Regulated Substances (29 CFR 1910.1001-1050)

Not regulated.

US EPCRA (SARA Title III) Section 313 - Toxic Chemical: Listed substance

n-hexane (CAS 110-54-3)

CERCLA Hazardous Substance List (40 CFR 302.4)

n-hexane (CAS 110-54-3) Listed.

CERCLA Hazardous Substances: Reportable quantity

n-hexane (CAS 110-54-3) 5000 LBS

Spills or releases resulting in the loss of any ingredient at or above its RQ require immediate notification to the National Response Center (800-424-8802) and to your Local Emergency Planning Committee.

Clean Air Act (CAA) Section 112 Hazardous Air Pollutants (HAPs) List

n-hexane (CAS 110-54-3)

Clean Air Act (CAA) Section 112(r) Accidental Release Prevention (40 CFR 68.130)

Not regulated.

Safe Drinking Water Act

(SDWA)

Not regulated.

Food and Drug Not regulated.

Administration (FDA)

Superfund Amendments and Reauthorization Act of 1986 (SARA)

Section 311/312 Immediate Hazard - Yes
Hazard categories Delayed Hazard - Yes
Fire Hazard - Yes
Pressure Hazard - Yes
Reactivity Hazard - No

SARA 302 Extremely hazardous substance

US state regulations

US. California. Candidate Chemicals List. Safer Consumer Products Regulations (Cal. Code Regs, tit. 22, 69502.3, subd.

liquefied petroleum gas (CAS 68476-86-8)

lubricating oils (petroleum), C15-30, hydrotreated neutral oil-based (CAS 72623-86-0)

naphtha (petroleum), hydrotreated light (CAS 64742-49-0)

No

n-hexane (CAS 110-54-3) petrolatum (CAS 8009-03-8)

US. New Jersey Worker and Community Right-to-Know Act

2-methylpentane (CAS 107-83-5)

naphtha (petroleum), hydrotreated heavy (CAS 64742-48-9) naphtha (petroleum), hydrotreated light (CAS 64742-49-0)

n-hexane (CAS 110-54-3) Paraffin oils (CAS 8012-95-1)

US. Massachusetts RTK - Substance List

2-methylpentane (CAS 107-83-5)

naphtha (petroleum), hydrotreated light (CAS 64742-49-0)

n-hexane (CAS 110-54-3)

white mineral oil (CAS 8042-47-5)

US. Pennsylvania Worker and Community Right-to-Know Law

2,2-dimethylbutane (CAS 75-83-2)

2,3-dimethylbutane (CAS 79-29-8)

2-methylpentane (CAS 107-83-5)

3-methylpentane (CAS 96-14-0)

naphtha (petroleum), hydrotreated light (CAS 64742-49-0)

n-hexane (CAS 110-54-3) Paraffin oils (CAS 8012-95-1) white mineral oil (CAS 8042-47-5)

US. Rhode Island RTK

naphtha (petroleum), hydrotreated heavy (CAS 64742-48-9) naphtha (petroleum), hydrotreated light (CAS 64742-49-0)

n-hexane (CAS 110-54-3)

Paraffin oils (CAS 8012-95-1)

petrolatum (CAS 8009-03-8)

white mineral oil (CAS 8042-47-5)

US. California Proposition 65

WARNING: This product contains a chemical known to the State of California to cause cancer and birth defects or other reproductive harm.

US - California Proposition 65 - CRT: Listed date/Carcinogenic substance

benzene (CAS 71-43-2) Listed: February 27, 1987

US - California Proposition 65 - CRT: Listed date/Developmental toxin

benzene (CAS 71-43-2) Listed: December 26, 1997

US - California Proposition 65 - CRT: Listed date/Male reproductive toxin

benzene (CAS 71-43-2) Listed: December 26, 1997

Material name: TAC 2® Adhesive Chain Lubricant

SDS US

Volatile organic compounds (VOC) regulations

EPA

VOC content (40 CFR 88.5 %

51.100(s))

Consumer products Not r

(40 CFR 59, Subpt. C)

Not regulated

State

Consumer products This product is regulated as a Gear, Chain or Wire Lubricant (aerosol). This product is not

compliant to be sold for use in California. This product is compliant in all other states.

VOC content (CA) 81.3 % **VOC content (OTC)** 81.3 %

International Inventories

Country(s) or region	Inventory name	On inventory (yes/no)*
Australia	Australian Inventory of Chemical Substances (AICS)	Yes
Canada	Domestic Substances List (DSL)	Yes
Canada	Non-Domestic Substances List (NDSL)	No
China	Inventory of Existing Chemical Substances in China (IECSC)	Yes
Europe	European Inventory of Existing Commercial Chemical Substances (EINECS)	No
Europe	European List of Notified Chemical Substances (ELINCS)	No
Japan	Inventory of Existing and New Chemical Substances (ENCS)	No
Korea	Existing Chemicals List (ECL)	Yes
New Zealand	New Zealand Inventory	Yes
Philippines	Philippine Inventory of Chemicals and Chemical Substances (PICCS)	Yes

^{*}A "Yes" indicates that all components of this product comply with the inventory requirements administered by the governing country(s) A "No" indicates that one or more components of the product are not listed or exempt from listing on the inventory administered by the governing country(s).

Toxic Substances Control Act (TSCA) Inventory

16. Other information, including date of preparation or last revision

Issue date04-10-2015Revision date01-24-2017Prepared byAllison Cho

Version # 03

United States & Puerto Rico

Further information CRC # 932A-B
HMIS® ratings Health: 2*
Flammability: 4

Physical hazard: 0 Personal protection: B

NFPA ratings Health: 2

Flammability: 4 Instability: 0

NFPA ratings



DisclaimerThe information contained in this document applies to this specific material as supplied. It may not

be valid for this material if it is used in combination with any other materials. This information is accurate to the best of CRC's knowledge or obtained from sources believed by CRC to be accurate. Before using any product, read all warnings and directions on the label. For further clarification of any information contained on this (M)SDS consult your supervisor, a health & safety

professional, or CRC Industries, Inc..

Revision InformationThis document has undergone significant changes and should be reviewed in its entirety.

Yes